

RISK ASSESSMENT FOR; PAMELA HAMBRO HALL DETAILS. WEST STREET WINTERBORNE STICKLAND DT11 ONT	ASSESSMENT REVIEW DATE <i>10-5-2010</i>	EXISTING CONTROLS. INFORMATION
	SIGNED..... <i>[Signature]</i>	CONTROLLED RISKS ACTION NEEDED

SIGNIFICANT HAZZARDS

**PEOPLE WHO ARE AT
RISK, FOM SIGNIFICANT
HAZZARDS**

**EXISTING CONTROLS
CONTROLLED RISKS
ACTION NEEDED (IF ANY)**

FIRE

**Hall Committee, Cleaner,
General Public, Doctor,
Staff, and Patients using PHH**

**Evacuation procedures
as per P.H.H. Handbook**

ELECTRICAL EQUIPMENT

As Above

*NEW HEATERS IN
TOILETS. COAT
HOOKS ABOVE
REMOVED*

**Check appliances leads
And plugs, including earth
Connections & wiring. Fit
Plug covers, to all exposed
13 amp sockets**

HALL SEATING

As Above

**Chairs are not to be stacked
More than 6 high.
Check signs stating "Danger
Hot Water"**

LADDERS AND STEPS

As Above

**No Wall Ladders to be used
Step ladder supplied to be
Used in accordance with
HSE. Guide INDG 402 2005
'Safe use of Step ladders'
And associated booklets**

OVERHEAD GANTRY

As Above

**Each suspended item to be
Individually chained and secured**

FLOORS

As Above

**All spillages to be cordoned off
Until cleaned up. Must be kept
Free from debris, checked for
Damage or instability**

Continued..

No agents to be used to
Increase floor friction, i.e.
Sanding

EMERGENCY EXITS

As Above

All emergency Exits to be
Kept clear at all times.
And emergency lights working

FIRE EXTINGUISHERS

As Above

All in correct position and
checked

Comment

All correct AT TIME OF CHECK

JL Workley